STEP 1 - INITIAL PREPARATION:

WITH THE HELP OF ANOTHER PERSON, PLACE THE TOP PANEL ON A CLEAN, FLAT SURFACE, WITH THE INNER SIDE FACING UP.

STEP 2 - LEG ATTACHMENT:

ALIGN ONE OF THE LEGS WITH THE PRE-DRILLED HOLES ON THE TOP PANEL. USING A DRILL, INSERT AND TIGHTEN THE SCREWS INDICATED IN DETAIL B1. REPEAT THIS STEP FOR THE SECOND LEG.

STEP 3 - FINAL PLACEMENT:

"ONCE BOTH LEGS ARE PROPERLY SECURED, PROCEED TO POSITION THE TABLE AT THE DESIRED LOCATION WITHIN THE INSTALLATION AREA.

IFD8841CKT / IFD4851CKT / IFD8841CKTDL / IFD4851CKTDL		
DESCRIPTION	#	
HEXAGONAL HEAD WOOD SCREWS 5/16 X 1-1/4"	8	
IFD8841END / IFD4851END		
DESCRIPTION	#	
HEXAGONAL HEAD WOOD SCREWS 5/16 X 1-1/4"	4	
IFD8841CST / IFD4851CST		
DESCRIPTION	#	
HEXAGONAL HEAD WOOD SCREWS 5/16 X 1-1/4"	4	
IFD8841CST / IFD4851CST		
DESCRIPTION	#	
HEXAGONAL HEAD WOOD SCREWS 5/16 X 1-1/4"	4	



ASSEMBLY INSTRUCTIONS

R1

[B]

HEXAGONAL HEAD WOOD

SCREWS 5/16 X 1-1/4"

I-MIX-E016

1

۰<u>.</u>

_	
5	
)	

4

3

2

[A]

Q

1

DETAIL B1 ESCALA 1 : 5

۰.